

## Laser Transfer Paper for Dark & Light Fabrics (HITEMP-PLUS Laser Opaque)

### Instructions

HiTemp Plus® Opaque *For printers and copiers with or without fuse oil*



HiTemp Plus® Opaque paper has a high level of opacity for dark fabrics. It is a durable and flexible material, cuttable with desktop and professional vinyl cutters for cut contours. It washes well and has a soft-hand.

- **Peels:** Hot and Cold
- **Finish:** Matte or Glossy (depending on cover sheet)
- **Recommended Fabrics:** Dark-colored cotton, polyester, poly/cotton, Lycra® & Nylon
- **Recommended Printers:** Color laser copiers and printers
- **Sizes:** 8.5x11 (A4), 11x17 (A3)
- **Recommended Items:** [Laser OPAQUE Transfer Papers](#) are designed to press images to:
  - Dark T-shirts, Sweatshirts, Mouse Pads, Coasters, Puzzles, Handbags, Binders, Pad folios, Paper products, Leather, Magnets, Wood veneer, Nylon Bags and more.
  - Always Choose garments that have a tight weave. This is particularly important when transferring to sweatshirts.
  - *IMPORTANT: Make one shirt and wash it by itself before producing your order.*



### PRINTING

1. **DO NOT Mirror** the image.
2. Load the paper so that the image will appear on the coated side of the paper.
3. Laser-OPAQUE Paper should be fed in via MULTI-Purpose Tray if possible.
4. Print Setting: use LABELS 1 or 2 depending on your Laser Printer may require Heavy Paper setting.
5. After contour cutting on your cutter, slowly peel the paper backing from the transfer film, starting with a small tear in the corner to make separating easier.

### TRANSFERRING

#### Using a Commercial Heat Press (only)

1. Place the transfer sheet face-up on the substrate and cover it with a Teflon, Silicone or Parchment paper (sold separately) and then press for: **12sec at 330°F using Medium pressure.**
2. Press **must** snap closed **firmly**.
2. Allow to cool completely before removing the Transfer Application tape, Silicone or Parchment paper.

**TRANSFER - Using a COMMERCIAL HEAT PRESS only!**

#### WASHING INSTRUCTIONS

Turn garment inside out and wash in cold water using a mild detergent. Does not use bleach. Dry on low heat setting. Do not iron directly on the transferred area.

#### STORAGE AND HANDLING OF Laser-OPAQUE HEAT TRANSFER PAPERS

Store Laser-OPAQUE Papers in a cool, dry area and do not remove from carton or poly bag until you are ready to use.